


Table B-1. 387 3048 Seal Replacement Kit

Oracle No.	Ruska Part Number	Description	QTY	DWG ID
3865053	54-700-259	O-RING BUNA N 6-1/4 X 1/8	1	1
3896283	2460-7-2	GASKET, BELL JAR BOTTOM	1	2
3865011	54-700-22	O-RING BUNA N 1 X 1/16	1	3
3865048	54-700-239	DRIVE BELT	1	4
3900227	24-649	FITTING FILTER DISC, BRASS	1	5
3865261	54-703-119	O-RING VITON 15/16 X 3/32	1	6
3865027	54-700-227	O-RING BUNA N 2 1/8 X 1/8	1	7
3865454	54-703-6	O-RING VITON 3/8 X 1/4 X 1/16	2	8
3864782	54-700-111	O-RING BUNA N 7/16 X 3/32	1	9
3865195	54-703-10	O-RING VITON 1/4 X 1/16	3	10
3899971	24-580	MEMBRANE FILTER	5	11
3865238	54-703-113	O-RING VITON 9/16 X 3/32	1	*
3872923	2460-6-156	RETAINING CLIP	3	*

* See Page B-9

Fluke recommends the unit is returned to the factory if items 7, 8, 9, or 10 need replacement.



glg46.bmp

Figure B-9. RUSKA 2465A-754 - Exterior View